

# TRAILERS & TANKERS PTY LTD

51 banfield Road Industria North Johannesburg  
011 730 8031  
REG 2020/866032/07 Vat :4520307945  
Manufacturing NO : 495100blb41



Warranty Approved cost to repair .

Adjusted 1 July 2023

The figures listed below are for repairs up to amount X , over this unit should be returned to supplier for assessment ,

these amount include total repair, Incorrect usage and abuse is NOT covered

Incorrect completed warranty claims will not be Honored.

## ☒ Tank:

- Welds: R 950
- Coating: R 1500
- Polyurethane tanks R 300

## ☒ Brake System:

- Brake Assembly: R 450
- Brake Lines: R 350

## ☒ Coupling System:

- Coupler: R 450
- Safety Chains: R 200

## ☒ Hose and Nozzle:

- Hose Connections: R 385
- Nozzle Assembly: R 450

# TRAILERS & TANKERS PTY LTD

51 banfield Road Industria North Johannesburg  
011 730 8031  
REG 2020/866032/07 Vat :4520307945  
Manufacturing NO : 495100blb41



## ☒ Meter:

- Calibration: R 250
- Wiring: R 450

## ☒ Filters:

- Installation: R 200

## ☒ Lighting and Electrical System:

- Wiring & Lights R 950

## ☒ Chassis and Structure:

- Alignment: R 950.
- Welds: R 950.

## ☒ Suspension System:

- Installation correction R 450

## ☒ Wheel Assembly:

- Bearing Installation: R 250
- Tire Mounting: R 250

Our warranty is designed to provide you with peace of mind against manufacturing defects and unforeseen issues that may arise from the normal use of the product. However, it is essential to understand that a warranty is not a maintenance agreement. Regular maintenance, as outlined in the product manual, is crucial to ensure the longevity, optimal performance, and safety of your product.

To keep the warranty valid, it is imperative that the product receives routine maintenance as recommended. Neglecting to perform regular maintenance may not only reduce the product's lifespan but might also void its warranty.

Please refer to the product's manual for a detailed maintenance schedule and guidelines. Adhering to these recommendations will ensure that your product remains in top condition and that you get the maximum benefit from the warranty should you ever need it.